

DELAWARE OFFICE:

2500 WRANGLE HILL ROAD FOX RUN OFFICE PLAZA, SUITE 110 BEAR, DE 19701 302.832.1652 PHONE 302.832.1423 FAX

ARCHITECTS ENGINEERS FACILITIES SOLUTIONS

ASI No. 6 – Phase 1A Misc. Credits

то	:	Conventional Builders
FROM	:	Dan Shurina
DATE	:	01/16/2024
REFERENCE	:	19121 East Wing HVAC Replacement at DelDOT Admin Bldg

Changes to Scope:

- 1. Delete installation of WSS-1 and HP-1. Turn equipment and purchased materials over to owner and provide credit for installation and omitted work and materials.
- 2. Delete removal and replacement of carpeting and vinyl base in Break Room E-230 (Drawing A-102). Provide credit proposal for omitted work.
- 3. Delete demolition of cabinet unit heaters in group bathrooms within the Phase 1A area (Drawing MD102A). Delete infill of metal stud wall, paint, and ceramic tile infill (Drawing A-102). Provide credit proposal for omitted work.

END